

	On Board Work			Parts Repair and Reconditioning Work					
	On Board Work	Dock S/V (Mechanical)	Eco SV	Fuel Nozzle Tip	Cyl. Lub. Oil Valve	Fuel Pump (Holder seat)	Exh. Valve	Cyl. Cover	Piston Head
Europe									
Germany									
Scan Motoren Handels und Service GmbH	○	—	—	—	—	—	—	—	—
Greece									
Konstantinos Kontogiannis & CO LP	○	—	—	—	—	○	○ * 2	○	○
Metlokast Hellas L.T.D	○	—	—	○	—	○	○ * 2	○	○
Italy									
La Meccanica Turbo Diesel S.r.l.	—	—	—	—	—	○	—	—	—
Netherlands									
Fuji Trading (Marine) B.V.	○	—	—	—	—	—	—	—	—
Goltens Rotterdam B.V.	○	—	—	—	—	—	○	○	○
Turkey									
Master Makina Ltd.	○	○	—	○	○	○	○ * 2	○	○
Orhan Sevim Matra Motor Yenileme San. A.Ş.	—	—	—	—	—	—	○	○	○
Middle East									
United Arab Emirates									
Albwardy Marine Engineering (LLC)	○	—	—	—	—	—	—	—	—
Diesel Marine International Dubai (LLC)	—	—	—	—	—	—	○	○	○
Goltens Co. Ltd. Dubai Branch	○	—	—	○	—	○	○	○	○
Nico International U.A.E.	○	—	—	—	—	—	—	—	—
Asia									
China									
Azuma Engineering (Shanghai) Co., Ltd.	—	—	—	—	—	—	—	—	○
Diesel Marine Dalian Ltd Nantong Branch	—	—	—	—	—	—	○	○	○
Fischer Engineering Co., Ltd.	○	—	—	—	—	—	—	—	—
Goltens Shanghai Co., Ltd.	○	—	—	○	—	○	○ * 2	○	○
Ningbo Diesel Marine Services Co., Ltd.	—	—	—	—	—	—	○ * 2	○	○
Qingdao Longkong Polestar Marine Engineering Co., Ltd.	—	—	—	—	—	—	○ * 2	○	○
Shanghai Henry Marine Service Co., Ltd.	○	—	—	—	—	—	—	—	—
Toei Engineering (Shanghai) Co., Ltd.	—	—	—	—	—	—	○ * 2	○	○
WinKong Marine Engineering Co., Ltd.	○	○	○	—	○	—	○	○	○

	On Board Work			Parts Repair and Reconditioning Work					
	On Board Work	Dock S/V (Mechanical)	Eco SV	Fuel Nozzle Tip	Cyl. Lub. Oil Valve	Fuel Pump (Holder seat)	Exh. Valve	Cyl. Cover	Piston Head
Asia									
Japan									
Azuma Machinery Co., Ltd.	—	—	—	○	—	○	—	—	—
Azuma Kako Co., Ltd.	—	—	—	○	—	○	○ * 2	○	○
Hakuyo Seiko Co., Ltd.	—	—	—	○	○	○	—	—	—
Polestar Marine Engineering Co. Ltd.	—	—	—	—	—	—	○ * 2	○	○
Spindle Giken Co., Ltd.	—	—	—	○	○	○	—	—	—
Toei Engineering Co., Ltd.	○	○	—	—	—	—	○ * 2	○	○
Singapore									
AC Marine Pte Ltd.	○	○	—	—	—	—	—	—	—
Azuma Engineering (S) Pte. Ltd.	—	—	—	○	—	○	○ * 2	○	○ * 1
Brightsun Marine Pte Ltd.	○	○	—	—	—	—	○	○	○
Daikai Engineering Pte. Ltd.	○	—	—	—	—	—	—	—	—
Goltens Singapore Pte. Ltd.	○	—	—	—	—	○	—	—	—
Goltens Toei Singapore Pte. Ltd.	—	—	—	—	—	—	○ * 2	○	○
Spindle Giken (S) Pte. Ltd.	○	—	—	○	○	○	—	—	—
South Korea									
Jonghap Polestar Engineering Co. Ltd.	—	—	—	—	—	—	○	○	○
TS Marine Co., Ltd.	○	—	—	—	—	—	—	—	—
Taiwan									
Azuma Engineering Ltd.	—	—	—	○	—	—	○ * 2	○	○
Thailand									
BOS Marine Co., Ltd.	○	—	—	—	—	—	—	—	—
North America									
Canada									
Marine Tech Industries Ltd.	○	—	—	—	—	—	○ * 2	—	○
United States of America									
Goltens Service Co., Inc. Miami	○	—	—	○	○	—	○	○	○
Motor-Services Hugo Stamp, Inc.	○	—	—	—	—	—	○	○	—
Shipworx Engineering LLC	○	—	—	—	—	—	—	—	—
United World Enterprise, Inc.	○	○	—	—	—	—	—	—	—
South America									
Brazil									
Metalock Brasil Ltda.	○	—	—	—	—	—	○	○	○

○ : Available

— : Not available

○ * 1 : Helical & Roll process available for Piston threar

○ * 2 : Available for repairing combustion surface of nimonic exhaust valve spindle